SECTION 1 MATERIAL IDENTIFICATION AND USE						
MATERIAL NAME IDENTIFIER: Cadmium Bearing Brazing Alloys						
Manufacturer's Name: MA	HESHWARI SMELTI	NG Street Add	dress: 17/17	75 SASNI GATE ALIGARH		
City: ALIGARH	Province/State/Country: U.P. (INDIA) Emergency Phone No: +91-9634317661					
Supplier's Name:	Street Address:					
City:	Province/State/Country: Emergency Phone No:					
Chemical Name: Silver Brazing Filler Metal		Chemical Family: Cadmium-Free Silver Brazing Alloys		Chemical Formula: Refer To Chart		
Molecular Weight: N/Avl.		Trade Names, Synonyms: Refer To Chart		Material Use: Filler Metals For Brazing		
SECTION 2 HAZARDOUS CHEMICAL COMPONENTS						
Chemical Component	CAS Number	(Refer to filler metal	chart bel	ow for nominal composition %)		
SILVER (Ag)	7440-22-4	ACGIH: TLVs (2000) 0.1 mg/m ₃ OSHA PEL: 0.01 mg/m ₃ TWA LD ₅₀ N/AvI.	TWA (meta	l) LC 50 N/AvI.		
COPPER (Cu)	7440-50-8	ACGIH: TLVs (2000) 0.2 mg/m3 TWA (fume); 1.0 mg/m3 TWA (dusts & mists) OSHA PELS: 0.1 mg/m3 TWA (fume); 1.0 mg/m3 TWA (dusts & mists) LD 50 470 mg/kg oral-mouse LC 50 N/Avl.				
ZINC (Zn)	7440-66-6		TWA as Zn TWA as Zn	O fume; 10 mg/m3 STEL as ZnO fume		
CADMIUM (Cd)	7440-43-9		з TWA; 0.00	02 mg/m ₃ TWA (respirable fraction)		
PHOSPHORUS (P)	7723-14-0	ACGIH: TLVs (2000) 0.1 mg/m3 OSHA PELS: 0.1 mg/m3 TWA LD 50 470 mg/kg oral-m				

	SILVER BRAZING FILLER METALS CHART									
FILLER METAL	AWS / SFA	Nominal Composition, %		Solidus (Melt Point) °F°C	Liquidus (Flow Point) °F°C	Brazing Range	Specific			
NAIVIE	CLASS	Ag	Cu	Zn	Cd	Others	, ,	F C	°C	Gravity g/cm3
Silver 67Cd	-	67	11	12	10	-	1175-635	1330-720	635-720	9.9
Silver 50Cd	BAg-1a	50	15.5	16.5	18	-	1150-620	1185-640	620-640	9.5
Silver 45Cd	BAg-1	45	15	16	24	-	1125-605	1150-620	605-620	9.4
Silver 44Cd	-	44	27	13	15	1P	1105-595	1220-660	595-660	9.3
Silver 43Cd	-	43	16	20	21	-	1140-615	1150-620	615-620	-
Silver 40Cd	-	40	19	21	20	-	1105-595	1165-630	595-630	9.3
Silver 38Cd	-	38	20	22	20	-	1125-605	1200-650	605-650	9.2
Silver 35Cd	BAg-2	35	26	21	18	-	1130-610	1295-700	610-700	9.1
Silver 30Cd	BAg-2a	30	28	21	21	-	1115-600	1270-690	600-690	9.2
Silver 251Cd	BAg-33	25	30	27.5	17.5	-	1125-605	1260-680	605-680	8.8
Silver 250Cd	BAg-27	25	35	26	14	-	1125-605	1375-745	605-745	9.0
Silver 20Cd	-	20	40	25	15	-	1125-605	1410-765	605-765	8.8
Silver 12Cd	-	12	50	31	7	-	1150-620	1520-825	620-825	8.5
Silver 5Cd	-	5	-	-	95	-	635-335	735-392	335-392	8.9

SECTION 3

SECTION 4

PHYSICAL DATA

Physical State: Gas ☐ Liquid Solid Odour Threshold (ppm): N/Avl. Evaporation Rate: Solid - N/Appl. % Volatile (By Volume): N/Appl. Specific Gravity: Refer To Chart

Odour & Appearance: No Odour; Solid Metal Wire, Strip, Powder, Paste Vapour Pressure (mm.Hg): N/Avl. Boiling Point (°C): Solid - N/Appl. Solubility In Water (20°C): Insoluble Coeff.-Water Oil Disp.: N/Appl.

Vapour Density (AIR=1):Solid-N/Appl. Freezing Point (°C): Solid – N/Appl.

pH: N/Appl.

FIRE AND EXPLOSION DATA

Flammability: Yes ■ No If yes, under which conditions?

Dust, powder and fumes are flammable when exposed to flame or by chemical reaction with oxidizing agents (see Section 5 for incompatible materials). Fires or explosions involving these alloys may release potentially toxic emissions of metal or metal oxide fumes (see Section 2 for hazardous components).

Means Of Extinction: Dry powder for metal fires. Do not use water on dust, powder or fume fires.

Special Procedures: Use self-contained breathing apparatus with full face-piece operated in pressure demand or other positive pressure

Flashpoint(°C) & Method: Solid Metal - Non-Flammable Lower Explosion Limit (%By Volume): Solid Metal-N/Appl. TDG Flammability Classification: None Sensitivity To Impact Explosion Data: N/Appl.

Upper Explosion Limit (% By Volume): N/Appl. Auto Ignition Temperature (°C): Solid Metal - N/Appl. Hazardous Combustion Products: Solid Metal - N/Appl.

Rate Of Burning: N/Appl.

Explosive Power: N/Appl. Sensitivity To Static Discharge: N/Appl.

SECTION 5

REACTIVITY DATA

AVOID DISPERSION OF FINELY DIVIDED PARTICLES IN AIR

Chemical Stability: Yes ■ No If yes, under which conditions? Normal Ambient Environment.

If yes, which ones? Incompatibility With Other Substances: Yes No

Strong Oxidizers: Se: Te: Mg: Chlorates: NH3: HNO3: Azides: Ethanol: Ethylenimine: CIF3: Inorganic and Organic Peroxides: Peroxyformic Acid; Chlorine and Fluorine; Permonosulphuric Acid; CrO₃; Mn and Ca Chlorides; CS₂; Hydrazine Mononitrate; Nitrobenzene; Fe (CO)₅; Seleninyl Bromide.

Reactivity And Under What Conditions: Stable under normal temperatures and pressures.

Hazardous Decomposition Products: Hazardous polymerization will not occur. Upon heating, danger is mostly from inhalation of metal (oxide) fumes. Overexposure to elemental oxide fumes or dust can cause nausea and metal fume fever. Use hooded exhaust ventilation to carry all fumes away from work area and, if necessary, use air supplied respirator (see Section 7). Thought should be given to the heating methods, flux and base metals being joined which could emit fumes on heating depending on their particular chemistry. Avoid overheating (see chart, Brazing Range).

SECTION 6

TOXICOLOGICAL PROPERTIES

Inhalation Inhalation of the components of these products are not known to present a significant risk to health **Route Of Exposure:** when used according to instructions and with appropriate protective measures (see Section 7). Inhalation of the component/elements has been reported to cause one or more of the following symptoms/effects upon excessively high and/or prolonged inhalation/exposure.

SILVER: May cause grey discolouration of mucous membranes. Acute

Chronic May produce argyria, a permanent blue-grey discolouration of the skin, eyes, mucous membranes,

and the respiratory tract.

COPPER: Acute exposure to dust or fume may cause respiratory tract irritation, fever, muscle ache, chills, Acute

cough, weakness, and a metallic taste.

Chronic Exposure may cause damage to the liver, kidney, spleen, pancreas, and brain.

ZINC: Acute Exposure to zinc oxide fume may cause respiratory tract irritation and "metal fume fever", which is

characterized by one or more of the following symptoms: metallic taste, dry throat, cough, chills,

fever, tightness of chest, dyspnea, headache, nausea, vomiting, and fatigue.

Chronic Exposure unlikely.

CADMIUM: Acute exposure to cadmium oxide fume by inhalation may produce pneumonitis, tracheobronchitis, Acute

and pulmonary edema.

Chronic Continued overexposure to cadmium (dust or fume) may produce gastrointestinal symptoms,

anemia, rhinitis, discolouration of teeth, micro fractures, kidney disease and cancer.

NICKEL: Acute Dust or fumes may produce headache, nausea, vertigo, asthma, and pulmonary edema.

Chronic May increase the risk of cancer to the nasopharynx, lungs, prostate, and kidney.

SECTION 6 (Cont'd) TOXICOLOGICAL PROPERTIES

Miscellaneous Toxicological Information

<u>Cadmium</u> is regulated as a carcinogen by the Occupational Safety and Health Administration per 29CFR 1910.1027. It is also classified as a potential human carcinogen by the following organizations (with respective sub-classifications):

- 1. IARC (Group 1)
- 2. NTP (Groups 2A & 2B)

Cadmium has been found to cause reproductive abnormalities, including reduced birth weights, reduced viability, and behavioural alterations among offspring of female rodents. Male rodents exposed to Cadmium have been found to have testicular damage, reduction in sperm counts, and reduced fertility. Cadmium has also produced mutagenic effects in mammalian cell cultures.

Nickel is classified as a potential human carcinogen by the following organizations (with respective sub-classifications):

- 1. IARC (Group 2B)
- 2. NTP (Group 2B)

Nickel has also produced fetotoxic and teratogenic effects in animal studies, and mutagenic responses in mammalian cell cultures. Neither Silver, Copper, Phosphorous, nor Zinc are classified as potential or demonstrated human carcinogens by IARC, NIOSH, NTP, OSHA, or ACGIH.

Health Conditions Aggravated By Exposure: Pre-existing pulmonary diseases (e.g., bronchitis, emphysema) may be aggravated by inhalation exposure to these materials, particularly as fume. Exposure to nickel by inhalation and/or ingestion may aggravate pre-existing disease of the liver, kidneys, central nervous system, and musculoskeletal system.

Route Of Exposure

Skin: In solid form, materials are not known to be hazardous. In finely divided form, skin contact may produce localized irritation, localized argyria, skin discolouration, and contact or allergic dermatitis.

Eyes: Exposure of the eyes to finely divided form of these materials may produce localized argyria, irritation, conjunctivitis, and ulceration of the cornea.

Ingestion: Finely divided form of these materials may produce gastric irritation, vomiting, abdominal pain, hemorrhage, and diarrhea. Long-term chronic ingestion may produce damage to the liver, kidney, spleen, pancreas, musculoskeletal system, blood-forming organs, and central nervous system.

LD 50 Of Material Specify Species And Route: N/Avl.	LC 50 Of Material Specify Species: N/Avl.	Exposure Limit Of Material: N/Avl.	Irritancy Of Material: N/Avl.
Sensitizing Capability Of Material: N/Avl.	Carcinogenicity Of Material: N/Avl.	Reproductive Effects Of Material: N/Avl.	Synergistic Materials: N/Avl.

SECTION 7

PREVENTATIVE MEASURES

Personal Protective Equipment: Personal protective equipment will be required when using these materials. The nature of the processing activity will determine what form of equipment is necessary, i.e., safety glasses, respirator, protective clothing, etc. Personal protective equipment should not be substituted for proper handling and engineering controls.

Gloves: Wear appropriate protective gloves to prevent injury from the hazards of brazing and/or repeated contact with finely divided material. Avoid flammable fabrics.

Respiratory: Local exhaust, mechanical ventilation, and/or respiratory equipment may be required to maintain a protection factor appropriate to the airborne concentrations of the contaminants generated and provide sufficient clean air for breathing. If exposure levels exceed OSHA PELS, wear a NIOSH/MSHA-approved respirator (or other approving authority) for protection from the airborne contaminants. All adjacent persons in the immediate vicinity of brazing or "soldering" operations shall be similarly protected as necessary by ventilation or approved respirators.

Eyes: Wear eye protection (safety glasses, dust-proof goggles) adequate to prevent eye contact with this material in finely divided form and to prevent eye injury from the hazards of brazing. Plastic-frame safety spectacles with side shields and filter lenses (shade #3 or #4) are recommended.

Footwear: Refer to workplace safety regulations.

Clothing: Avoid flammable fabrics. Wear appropriate clothing to prevent skin injuries from the hazards of brazing.

Other Protection: Practice good housekeeping and personal hygiene procedures. To avoid ingestion of material, wash hands and face before eating, drinking, or consumption of tobacco. Brazing alloys may be used with a separately applied flux which, when heated, may emit irritating and/or toxic gases and fumes. Consult the MSDS for the specific flux in use to determine its hazards and appropriate protective measures. For general guidance, refer to American National Standards Institute (ANSI) Z49.1, "Safety in Welding and Cutting" (American Welding Society, Miami, FL 33135).

Engineering Controls: Adequate ventilation, sinks, showers, and eyewash stations should be provided. The best industrial control practice is to maintain concentrations of all chemical fumes and dusts as low as is practical.

Leak And Spill Procedure: If metal is molten, allow to solidify and cool. Clean up any spilled material so as to minimize dispersion of dusts. Wet sweeping or vacuuming using HEPA, or similarly approved filtration, are recommended methods.

SECTION 7 (Cont'd)

PREVENTATIVE MEASURES

Waste Disposal: Return to manufacturer for reclaim. Sara Title III - Hazard Classes: Acute Health Hazard; Chronic Health Hazard Handling Procedure And Equipment: Avoid heating above brazing range (see chart, Section 2) as excessive fumes may result. Zinc boils at 1665°F/910°C) Use sufficient flux or atmosphere to protect the metals and minimize oxidation/vapourization during use.

Storage Requirements: Avoid storage near incompatible materials (see also Section 5). Also avoid conditions which create toxic fumes or dusts. Wash exposed skin after handling material. Stable at room temperature.

Special Shipping Information: No special requirements. WHMIS Classification: Class D, Division 2, Subdivision B.

SECTION 8

FIRST AID MEASURES

Emergency And First Aid Procedures

Inhalation: Move victim to fresh air at once. Give oxygen if breathing is laboured, artificial respiration if victim is not breathing. Keep person warm and quiet. Get medical attention immediately.

Skin: Contact in solid forms is not known to be hazardous. If clothing is contaminated with finely divided particles, remove. Wash affected area with large quantities of water for at least 5 minutes. Get medical attention if necessary.

Eyes: Flush immediately with large amounts of water for at least 15 minutes while lifting the lower and upper eyelids. If irritation continues, get medical attention.

Ingestion: If person is conscious, give large amounts of water and induce vomiting. Seek medical attention. If person is unconscious or convulsive, get immediate medical attention.

SEEK MEDICAL ATTENTION IN ALL CASES OF EXPOSURE SIGNS AND SYMPTOMS OF EXPOSURE:

Acute

Inhalation: Chills, fever, aching muscles, sneezing, dry throat, coughing, constriction of throat, nausea, irritation of nose and trachea, discolouration of mucous membranes, difficulty in breathing, chest pain, headache.

Skin: Particles may cause irritation, pain, nausea, vomiting.

Eyes: Particles may cause irritation, redness, itching.

Ingestion: Nausea, vomiting, headache, diarrhea, fever, abdominal pain.

Chronic

Inhalation: Cough, difficulty in breathing, laryngitis, discolouration of mucous membranes, kidney and liver disorders.

Skin: May cause argaria, discolouration, contact dermatitis and/or allergic sensitization among hyper-susceptible individuals.

Eyes: Irritation. May cause, particularly in powder form, argaria, conjunctivitis, and/or ulceration of the cornea.

Ingestion: May cause damage to the liver, kidneys, musculoskeletal system and nervous system.

Medical Conditions Generally Aggravated By Exposure: (see Section 6).

Sources Used: Canadian Centre For Occupational Health And Safety, Hamilton, Ontario; American Welding Society, Miami, Florida; ACGIH, Cincinnati, Ohio;

Additional Information: The information contained herein is only for the manufactured product. The composition and hazards of any resultant fumes due to heating methods, filler metal alloy, flux and base metals employed may vary significantly.

Brazing fumes consist of various airborne substances which may create hazards to health when they are inhaled or swallowed. The degree of hazard to the worker(s) in the work area depends upon the composition of the total fume, the concentration of contaminants in the breathing air and the time-length of exposure to it. It is the responsibility of the user/employer to ensure the suitability of the material use and that TLV, TWA, and STEL values are not exceeded. Assessment of the possible exposure to the worker(s) to hazardous fumes, when required, should be carried out by a competent person and may involve air concentration measurements

SECTION 9	PREPARATION DATE OF	MSDS
PREPARED BY:	PHONE NO:	DATE:
Marketing Department	+91-9634317661	Revised 8/08